PCIe x16 lane status: GEN2, Reduced Lanes (sent to Nuno Cláudio for soldering checkup 2014/03/25)