

ITEM	STATUS	COMMENT
<b>Components</b>	Standard	All components according to assembly plan
<b>EEPROM (U2)</b>	NOT INSTALLED	check if one is needed - ex: to disable PEX ports
<b>R916</b>	NOT PRESENT	no PEX configuration by I2C
<b>Firmware</b>	Programmed	"generic7.mcs"
<b>FW switch (SW5)</b>	(1111) RTM_FCLKA pcie source	for use with ATCA-PTSW-AMC4_RTM
<b>J36/J37</b>	ON	
<b>IPMC</b>	PRESENT	but does not handle cable PCIe reset
<b>Mechanics</b>	Assembled	but
<b>PCIe test</b>	OK	with <a href="#">ATCA-PTSW-AMC4 RTM v2.1 #4</a>
<b>LEDs</b>		Need to reverse order on the header connector.
<b>Current location</b>		