

ITEM	STATUS	COMMENT
Components	Standard	All components according to assembly plan
EEPROM (U2)	INSTALLED	upstream port = 1; station 0 x4x4x4x4; disable FPGA,AMC and unconnected ports
R916	NOT PRESENT	no PEX configuration by I2C
Firmware	Programmed	"generic7.mcs"
FW switch (SW5)	(1100) RTM_TCLKA PCIe source	for use with ATCA-PTSW-AMC4_844
J36/J37	ON	
IPMC	NOT PRESENT	
Mechanics	Assembled	
PCIe test	OK	with ATCA-PTSW-AMC4_844 prototype, cable, OSSx4
LEDs	ОК	
Current location	IST, Lisbon.	